


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

never set



Description of corner evidence found:

nothing

Description of monument and accessories established to perpetuate the original location of this corner

Set corner at position established per a survey by Century West Engineering Corporation under U.S.F.S. Contract #53-04H1-9-7306N.



Set 3" aluminum cap on 2 1/2" aluminum cap protruding 18" above ground from which:

2 new bearing trees:


N 64° E, 113.9 ft., 10" Ponderosa Pine scribed (C 1/4 S 11 BT), sign #54-3.

S 30° E, 118.8 ft., 10" Juniper scribed (C 1/4 S 11 BT), sign #54-3.

O.L.S. 1678 tag attached to all B.T.'s

I, Gary W. Hickman, P.L.S. 1678, certify the above corner monument was established as herein described in June of 1979.

Witness: Steve Miller, party chief and Steve Cortright, chainman



Office of Surveyor County of Gent
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 5 day of Oct, 1979, at 3 o'clock P.m., (signed)
Robert D. Smith by _____
(COUNTY OFFICIAL) (DEPUTY)