


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-7

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.



Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 20" in the ground and raised a mound of earth around the pipe.

From Which:

A Pine 18" dia., Bears S28°05'W., 75.4 ft., scribed: C1/4 S5 BT

A Juniper 22" dia., Bears S32°49'E., 85.1 ft., scribed: C1/4 S5 BT

Measurements to trees taken with an Electronic Tacheometer with angles turned from the survey control network.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, 4 ft. North & South from the corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

[Signature]
**OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848**

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: June 1, 1987
Refer to Map of Survey No. 1004

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 5 day of Oct, 1987
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)