


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. H-7

**History of original corner establishment:**

Grant County Survey Records show no previous establishment of this Cor.



**Description of corner evidence found:**

Grant County Survey Records show no previous establishment of this Cor.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 26" in the ground.

From Which:

Set 5/8"x30" iron pins with plastic caps stamped: PLS 848 SURVEY MARKER and steel guard posts with Warning and Bearing Tree signs, as follows:

North 7.0 ft. & East 7.0 ft. from the corner.

Measurements to pins taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*[Signature]*  
OREGON  
JULY 12, 1900  
DOUGLAS M. FERGUSON  
848

This work is performed by:  
Douglas M. Ferguson RLS 848  
Mt. Vernon Oregon.  
On: June 4, 1987  
Refer to Map of Survey No. 1004

Office of *Sauwajan* County of *Grant*  
State of *Oregon*, I hereby certify that the within instrument was filed in this office  
for record on the *2* day of *Oct*, 19*87*  
*Robert D. Buzette* by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)