

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by A. O. Eckelson, US Deputy Surveyor, during the original survey Joint Contract No. 366 dated August, 1880.

Set post for 1/4 Sec cor from which

A pine 30 ins diam bears S5°W, (15.8')24 lks dist

A pine 12 ins diam bears S45°E, (26.4')40 lks dist

DIAGRAM

T17S R30E

1/4
S 3 | S 2

1986
PLS 699

Description of corner evidence found:

No evidence of the original post was found.

30" pine & 12" pine (1880 BTs) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at single proportionate measurements from adjacent found corners. Built a mound of earth & rock to be 30" in diameter by 4" high around the monument, from which new BTs are:

6" Douglas-fir bears S16° 30'W, 11.8 feet scribed 1/4 S3 BT

11" Douglas-fir bears S54° 30'E, 44.9 feet scribed 1/4 S2 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet S of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on June 26, 1986, I re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 30 DAY OF Sept, 19 86

Robert D. Bayne
Grant County Surveyor