

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by A. O. Eckelson, US
Deputy Surveyor, during the original survey
Contract No. 366 dated August, 1880.

Set Post for cor To secs 2, 3, 10 & 11 from which

- A pine 6 ins diam bears S87E, (11.9') 18 lks dist
- A pine 36 ins diam bears S80°W, (11.9') 18 lks dist
- A pine 40 ins diam bears N76°W, (50.8') 77 lks dist
- A pine 6 ins diam bears N5°E, (23.8') 36 lks dist

DIAGRAM

T17S R30E

S 3	S 2
S10	S11

1986
PLS 699

Description of corner evidence found:

Post location fell in a skid road and no sign of the original corner monument could be found.

- 18" Ponderosa pine (Good Condition) (Blaze Healed Over) (1880 BT) bears N84°E, 11.9 feet
- 15" Ponderosa pine (Good Condition) (Blaze Opened by Others) (1880 BT) bears N12°E, 23.8 feet
- The 36" & 40" pine (1880 BTs) may be found stump holes, but not for certain and not required to locate the corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at the point determined by the bearing trees. Built a mound of earth to be 30" in diameter by 4" high around the monument, from which new BTs are:

- 8" Ponderosa pine bears S39°W, 77.3 feet scribed T17SR30E S10 BT
- 13" Ponderosa pine bears N43° 30'W, 25.5 feet scribed T17SR30E S3 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet W of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877,
do hereby certify that on June 1, 1986, I monumented
the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 30 DAY OF Sept, 1986

Robert D. Baggett
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers
OREGON
JULY 9, 1965
LELAND L. MYERS
699