

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US
Deputy Surveyor, during the original survey
Contract No. 384 dated March, 1881.
Set stone 24x14x10 in mound of stone for 1/4 sec
cor

DIAGRAM

T17S R31E

S $\frac{1}{4}$ S 4

1986
PLS 699

Description of corner evidence found:

18x10x8 rock with 1/4 chiseled into one face. The rock was laying about
4' west of a stone mound. It had been used as a fence anchor and still
had wire around it.

No bearing trees were previously established.

**Description of monument and accessories I established to perpetuate the
original location of this corner:**

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the
diagram, 24" in the ground to rock, replacing the rock which is turned
upside down and buried on the north side of the monument. Built a mound
of rock & earth to be 30" in diameter by 6" high around the monument.

No new bearing trees set because no trees are available.

1"x30" galvanized pipe with 2 1/2" aluminum cap Reference Monument bears North, 5.1 feet stamped RM 5.1' ↓

1"x30" galvanized pipe with 2 1/2" aluminum cap Reference Monument bears East, 4.3 feet stamped RM ← 4.3'

Set a steel fence post 5 feet N of the corner with an Attention sign
attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877,
do hereby certify that on May 12, 1986, I monumented
the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 6 DAY OF April, 1987

Robert D. Baggett
Grant County Surveyor

