

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-23

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T17S R31E
C 1/4

S 1

1992

PLS 848

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Douglas Fir, 12" dia., bears N66°50'W, 10.7 ft., scribed: C1/4 S1 BT
Douglas Fir, 14" dia., bears N56°44'E, 38.6 ft., scribed: C1/4 S1 BT
Douglas Fir, 14" dia., bears S42°21'E, 40.5 ft., scribed: C1/4 S1 BT
Douglas Fir, 12" dia., bears S19°35'W, 24.6 ft., scribed: C1/4 S1 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument. Nailed a brass washer stamped PLS 848 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs and painted blaze red.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1938
DOUGLAS M. FERGUSON
848

This work was performed by:
Douglas M. Ferguson PLS 848
Witnessed by: D. Mitchell Ferguson
and Rick Saul
May 19, 1992
Refer to Grant Co. Survey No.: 1218

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 16 day of Oct, 1992
Robert D. Sapp by _____
(COUNTY OFFICIAL) (DEPUTY)