

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-24

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T17S R31E
E1/16
C—•—C
S 1
1992
PLS 848

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 27" in the ground.

From Which:

Ponderosa Pine, 16" dia., bears N52°08'W, 16.8 ft., scribed: C-E 1/16 S1 BT
Ponderosa Pine, 12" dia., bears S12°38'W, 25.3 ft., scribed: C-E 1/16 S1 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north of the monument. Nailed a brass washer stamped PLS 848 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs and painted blaze red.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

This work was performed by:
Douglas M. Ferguson PLS 848
Witnessed by: D. Mitchell Ferguson
and Rick Saul
May 19, 1992
Refer to Grant Co. Survey No.: 1218

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 16 day of Oct, 1992
Robert D. Lantz by _____
(COUNTY OFFICIAL) (DEPUTY)