


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:



Description of corner evidence found:

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2 1/2" x 30" aluminum pipe with 3" aluminum cap rising 18" in stone mound. Monument set at South side of ledge rock and had Cap marked to be tipped North for correct positioning of top.

~~As~~ As witnesses:

*A 44" Ponderosa Pine bears S38°E
65.7' marked S 1/16 S1 BT
A 18" Ponderosa Pine bears N84°E
81.9' marked S 1/16 S1 BT*

*S $\frac{1}{16}$
S2 $\frac{1}{2}$ S1
1986
LS 1020*

"No trees available in Section 2"

Attached signs 54-3 & 54-9 to BTs; painted a red band around each and nailed brass discs marked LS 1020 to BT blazes.

I hereby certify the above corner point was established as described in November, 1986.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 2 day of Mar, 1987
Robert D. Bryant by _____
(COUNTY OFFICIAL) (DEPUTY)
See MOS 981

George W. Colvin, Jr.
REGISTERED
PROFESSIONAL
LAND SURVEYOR
FEBRUARY 14, 1975
GEORGE W. COLVIN, JR.
1020