

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. D-23

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T17S R31E
C
S1/16 S 1
C
1992
PLS 848

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown on the DIAGRAM, 18" in the ground and raised a mound of stone 1 1/2' high x 2' dia.

From Which:

Ponderosa Pine, 28" dia., bears N89°00'E, 254.4 ft., scribed:C-S 1/16 S1 BT
Ponderosa Pine, 10" dia., bears S09°41'E, 107.6 ft., scribed:C-S 1/16 S1 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' east and west of the monument. Nailed a brass washer stamped PLS 848 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs and painted blaze red.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1993
DOUGLAS M. FERGUSON
848

This work was performed by:
Douglas M. Ferguson PLS 848
Witnessed by: D. Mitchell Ferguson
and Rick Saul
May 19, 1992
Refer to Grant Co. Survey No.: 1218

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 6 day of Oct, 1992
Robert D. Engelt by _____
(COUNTY OFFICIAL) (DEPUTY)