

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US
Deputy Surveyor, during the original survey
Contract No. 384 dated March, 1881.
Set stone on bank of stream 15x12x10 in mound of
stone for cor to secs 8, 9, 16 & 17

DIAGRAM

T17S R31E

S 8	S 9
S 17	S 16

1986
PLS 699

Description of corner evidence found:

There is an old dam that crosses the corner location and other
agricultural activities in the area. Could not find any evidence of the
original corner. The nearby fence corner was nearly accepted, but due to
evidence that the fence had been moved it was not.

**Description of monument and accessories I established to perpetuate the
original location of this corner:**

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the
diagram, 26" in the ground on the east-face of the old dam, at double
proportionate measurements from adjacent found corners. Built a mound of
rock to be 12" in diameter by 4" high around the monument.

No new bearing trees set because no trees are available.

30" No. 5 rebar with 2" aluminum cap Reference Monument bears S47°E, 13.5 feet stamped RM 13.5' 1986 PLS 699

30" No. 5 rebar with 2" aluminum cap Reference Monument bears N35°E, 13.1 feet stamped RM 13.1' 1986 PLS 699

Set a steel fence post 5 feet E of the corner with an Attention sign
attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877,
do hereby certify that on November 16, 1986, I
re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 6 DAY OF April, 1987

Robert D. Baggett
Grant County Surveyor