

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by S. W. Lackland, US
Deputy Surveyor, during the original survey
Contract No. 384 dated March, 1881.

Set post with pits and mound for 1/4 sec cor as
per instructions

DIAGRAM

T17S R31E

1/4
S17|S16

1986
PLS 699

Description of corner evidence found:

The corner location falls in a meadow-hay field and all corner evidence is
gone.

**Description of monument and accessories I established to perpetuate the
original location of this corner:**

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the
diagram, 30" in the ground to be flush with the ground surface, at single
proportionate measurements from adjacent found corners.

No new bearing trees set because no trees are available.

Deposited two color-coded DEEP magnetic memorials 3' from the monument with silver to the NW and Purple to the NE 18" in
the ground to be below any agricultural activity. Reference Monuments are impractical at this corner.

Set a steel fence post 2 feet N of the corner with an Attention sign
attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877,
do hereby certify that on November 16, 1986, I
re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 6 DAY OF apr, 1987

Robert W. Bazzes
Grant County Surveyor