

RECORD OF LAND CORNER MONUMENTATION


CORNER: E $\frac{1}{4}$ Cor. Sec. 15, T.17S., R.31E., W.M.

ORIGINAL SURVEY BY: Samuel L. Lackland

CONTRACT NUMBER: 197

CONTRACT DATE: May 29, 1881

SUBSEQUENT SURVEY: Scott R. McIntyre 1979



ORIGINAL G.L.O. DESCRIPTION: Set stone 14x10x8 in mound of stone for $\frac{1}{4}$ sec. cor.

1979 RESURVEY BY SCOTT R. MCINTYRE, CADASTRAL SURVEYOR UNDER SPECIAL INSTRUCTIONS DATED 05/21/1979 (Pg. 370-371): SEE RECORD MAP OF SURVEY NO. 752.

Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 23 ins. in the ground, in a collar of stone, with brass cap mkd.

T 17 S R 31 E
 $\frac{1}{4}$
S 15 | S 14
1979

from which

A pine, 13 ins. diam., bears S. 72° E., 247 lks.
dist., mkd. $\frac{1}{4}$ S14 BT.

A pine, 24 ins. diam., bears S. 32° W., 149 lks.
dist., mkd. $\frac{1}{4}$ S15 BT.

EVIDENCE FOUND:

None. No field visit was made for this Corner Restoration Report, it has been prepared from record General Land Office and Bureau of Land Management field notes. See Record Map of Survey 752 filed in the Grant County Surveyor's Office.

PREPARED BY:

Michael C. Springer, PLS
Grant County Surveyor
Marcus Teague, Technician

217 N. Canyon Blvd.
John Day, OR, 97845
(541) 575-1251

December 20, 2016

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

DEC 27 2016

BY:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2018