

RECORD OF LAND CORNER MONUMENTATION


CORNER: SE Cor. Sec. 25, T.17S., R.31E., W.M.

ORIGINAL SURVEY BY: Henry W. Cooke

CONTRACT NUMBER: 494

CONTRACT DATE: January 16, 1884

SUBSEQUENT SURVEY: Scott R. McIntyre 1979



ORIGINAL G.L.O. DESCRIPTION: Set post 4 ft. long 4 ins. square with marked stone 12 ins. in the ground for cor. to secs. 25, 30, 31 & 36 marked T17S, S30 on N.E, marked R32E S31 on S.E, marked R.31.E. S36 on SW, marked S25 on NW faces, with 5 notches on the N., 1 notch on S. edges. Dug pits 18x18x12 ins. each sec. 5½ ft. dist. and raised a mound of earth 2 ft. high 4½ ft. base around post.

1979 RESURVEY BY SCOTT R. MCINTYRE, CADASTRAL SURVEYOR UNDER SPECIAL INSTRUCTIONS DATED 05/21/1979 (Pg. 348-349): SEE RECORD MAP OF SURVEY NO. 752.

Beginning at the cor. of secs. 25, 30, 31, and 36, on the E. bdy. of the Tp., at intersection of wire fences, extending N., E., and W. This position is harmoniously related to identified original corners and is accepted as the best available evidence of the position of the original corner.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

T 17 S	
R 31 E	R 32 E
S 25	S 30
S 36	S 31
1979	

EVIDENCE FOUND:

None. No field visit was made for this Corner Restoration Report, it has been prepared from record General Land Office and Bureau of Land Management field notes. See Record Map of Survey 752 filed in the Grant County Surveyor's Office.

PREPARED BY:

Michael C. Springer, PLS
Grant County Surveyor
Marcus Teague, Technician

217 N. Canyon Blvd.
John Day, OR, 97845
(541) 575-1251

December 23, 2016

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

DEC 28 2016

BY: 

