(86)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey

DIAGRAM

C-S 1/16

S 4

T17S R32E

No record of subsequent monumentation found in County records

Description of corner evidence found:

NONE

See survey dated October, 1981

Description of monument and accessories I established to perpetuate the original location of this corner:

At corner point I set a 2½ x 30 inch aluminum pipe with aluminum cap marked as shown 25 inches in the ground from which;

NEW BTs

A 36 inch P.Pine bears N32W, 12.2 feet marked CS 1/16 S4 BT

A 12 inch P.Pine bears S46W, 21.5 feet marked CS 1/16 S4 BT

Raised small mound of stone



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Date. October 2, 1981.

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of Secretary *County of* Grant

State of Oregon, *I hereby certify that the within instrument was filed in this office for record on the* 23 *day of* Dec, *19* 81

Robert D. Bugger *by* .....

(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

45 D-11