


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

76

History of original corner establishment:

Corner not established in original survey



No record of subsequent monumentation found in County records  
Description of corner evidence found:

NONE


See survey dated October, 1981  
Description of monument and accessories established to perpetuate the original location of this corner:

At corner point I set a 2 1/2 x 30 inch aluminum pipe with aluminum cap marked as shown 24 inches in the ground from which;

NEW BTs

A 14 inch P.Pine bears S7W, 17.9 feet marked CN 1/16 S8 BT

A 11 inch P.Pine bears N25W, 41.0 feet marked X BT



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Handwritten signature of Duane I. Griffith*

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
644

Date, October 2, 1981...  
Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of... *Sherwood* ... County of... *Grant* ...  
State of... *Oregon* ... I hereby certify that the within instrument was filed in this office for record on the... *23* day of... *Dec* ... 19*81*...  
*Robert W. Dwyer* by \_\_\_\_\_ (DEPUTY)  
(COUNTY OFFICIAL)