


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

75

History of original corner establishment:

Corner not established in original survey



No record of subsequent monumentation found in County records  
Description of corner evidence found:

NONE

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 10, 1984  
DUANE I. GRIFFITH  
644

See survey dated October, 1981  
Description of monument and accessories established to perpetuate the original location of this corner:

At corner point, which is in a road, I set a 2½ x 30 inch aluminum pipe with aluminum cap marked as shown, 37 inches in the ground, 7 inches below the road surface, from which;

NEW BTs


A 19 inch P.Pine bears S54W, 40.8 feet marked NE1/16 S8 BT

A 24 inch P.Pine with double bole bears N14W, 40.1 feet marked NE 1/16 S 8 BT

REFERENCE MONUMENTS

A 5/8 x 30 inch iron pin with plastic cap bears NO-06-37W, 47.24 feet, cap marked BGA SURVEY MARKER

A 5/8 x 30 inch iron pin with plastic cap bears S89-50-35W, 22.98 feet, cap marked BGA SURVEY MARKER



Date. October 2, 1981

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of Surveyor County of Grant  
State of Oregon I hereby certify that the within instrument was filed in this office for record on the 23 day of Dec, 1981  
Robert W. Degett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)