


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



No record of subsequent monumentation found in County records  
Description of corner evidence found:

NONE


See survey dated October, 1981  
Description of monument and accessories established to perpetuate the original location of this corner:

At corner point I set a 2 1/2 x 30 inch aluminum pipe with aluminum cap marked as shown 27 inches in the ground from which;

NEW BTs

A 12 inch P.Pine bears N60E, 14.1 feet marked X BT

A 10 inch P.Pine bears S13E, 7.0 feet marked CW 1/16 S8 BT



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Robert D. Budgett*

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
644

Date. October 2, 1981  
Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 23 day of Dec, 1981  
Robert D. Budgett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)