


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

18

History of original corner establishment:

Corner not established in original survey



No record of subsequent monumentation found in County records
Description of corner evidence found:

NONE


See survey dated October, 1981
Description of monument and accessories established to perpetuate the original location of this corner:

At corner point I set a 2½ x 30 inch aluminum pipe with aluminum cap marked as shown 30 inches in the ground from which;

NEW BT

A 28 inch P.Pine bears N84W, 327.0 feet marked W1/16 S8 BT

A 1" x 72" steel fence post driven 24 inches in the ground bears North 5.9 feet



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Handwritten signature
OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Date. October 3, 1981.
Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination in the establishment of accessories. New BTs measured to center of tree.

Office of..... *Sumner* County of..... *Grant*
State of..... *Oregon* I hereby certify that the within instrument was filed in this office
for record on the... *23* day of..... *April* , 19*81*.....
Robert D. Dwyer by
(COUNTY OFFICIAL) (DEPUTY)