

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. U-4

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T17S R32E
SE 1/16
•
S30
1992
PLS 848

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:



Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 27" in the ground.

From Which:

A 5/8" x 30" rebar, set 28" in the ground, with yellow plastic cap marked PLS 848 bears:

East, 10.3 ft. (no grooves on rebar)
South, 11.7 ft. (1 groove on rebar)

Measurements to rebars taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) sign and Property Boundary (54-2) sign 5' south and east of the monument. Set steel guard posts alongside each rebar reference with Bearing Tree (54-3) signs and Land Survey Monument (54-9) signs on each post.



This work was performed by:
Douglas M. Ferguson PLS 848
Witnessed by: D. Mitchell Ferguson
and Rick Saul
May 5, 1992
Refer to Grant Co. Survey No.: 1217

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 16 day of Oct, 1992
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)