

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. V-4

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T17S R32E  
S30  
E1/16—  
S31  
1992  
PLS 848

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 25" in the ground.

From Which:

North, 9.6 ft. (no grooves on rebar)  
South, 9.1 ft. (1 groove on rebar)

Measurements to rebars taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) sign and Property Boundary (54-2) sign 5' west and north of the monument. Set steel guard posts alongside each rebar reference with Bearing Tree (54-3) signs and Land Survey Monument (54-9) signs on each post.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1989  
DOUGLAS M. FERGUSON  
848

This work was performed by:  
Douglas M. Ferguson PLS 848  
Witnessed by: D. Mitchell Ferguson  
and Rick Saul  
May 5, 1992  
Refer to Grant Co. Survey No.: 1217

Office of Surveyor County of Grant  
State of OR I hereby certify that the within instrument was  
filed in this office for record on the 16 day of Oct, 1992  
Robert D. Baggett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)