


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original corner was established in 1883 by Henry W. Cooke.

Set basalt stone 20x20x5 ins. 15 ins in the ground for 1/4 sec cor marked 1/4 on N face. dug pits 18x18x12 ins E & W of Stone 5 1/2 ft dist and raised a mound of earth alongside.



Description of corner evidence found:

Found a 24x22x7 stone marked 1/4 lying flat on a southeast slope.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 3 1/2" x 30" aluminum monument with magnet in a mound of stone. Placed the original stone in the mound.

Set a 2" aluminum cap on rebar North 25.0 feet stamped T17S R32E 1/4 S32 RM SOUTH 25.0 PLS 1918 1985.

Set a 2" aluminum cap on rebar South 25.0 feet stamped T18S R32E 1/4 S5 RM NORTH 25.0 PLS 1918 1985.


Set a steel fence post with Attention sign West 3 feet.

Work performed 19 May 1985
 Witness: Louise H. Parsons

Tyler B. Parsons, PLS 1918
 1915 SE Stone Street
 Corvallis, OR 97333
 (503) 752-7515

Road Cadastral Survey, Cont No 53-04H1-4-9665N

CAP MARKED
 T17S R32E
 S32
 1/4 ———
 S5
 T18S
 PLS 1918
 1985



Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 19 day of June, 1985
Robert D. Bayliff by _____
 (COUNTY OFFICIAL) (DEPUTY)