CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Originally established by Barnford Robb in 1880 under Robb and Eckelson joint contract number 366, dated August 18, 1880. Surveyor General's records state :-

Set post for cor to secs 1, 12, 6 and 7 with pits and mound.

DIAGRAM



Description of corner evidence found:

None found.

Description of monument and accessories I established to perpetuate the original location of this corner:



Corner location re-established by single proportionment between found corners to the north and to the south. At this location I set a standard F.S. aluminum monument consisting of a 3" disk mounted on a 2x30" pipe with a 4x4½" footplate, buried 24" with 6" protruding above the ground. Disk is stamped as shown:

New BTs established:

A 10" Western Juniper bears N. 41° W. a distance of 40.3 feet, scribed T17S R28E S 1 BT

A 10" Western Juniper bears S. 53° W, a distance of 56.6 ftt, scribed T17S R28E S 12 BT

A 12" Western Juniper bears S. 22°30' E. a distance of 127.4 ft. scribed T17S R29E S 7 BT

A 20" Western Juniper bears N, 74°30' E., a distance of 120.3 ft. scribed T17S R29E S 6 BT

All are banded with red paint, carry BT and Attention signs and have a brass disk stamped PLS 1287 nailed to the base of the BT blaze.

Monument set 10/23/81

Witnesses: H.W. Palmer
P. Zabala

Monument set as part of U.S. Forest Service cadastral survey "Three Piece", see Survey Plat dated Nov. 1981, Grant County Survey No. 708.



Office of Surveyor *County of* Grant
State of Oregon, *I hereby certify that the within instrument was filed in this office for record on the* 18 *day of* Dec, *19*81.
Robert D. Sayers *by* .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276