


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: CORNER WAS ESTABLISHED IN AUGUST 1874 BY ALONZO GESNER UNDER GENERAL LAND OFFICE CONTRACT No. 206.

NOTE: NO BEARING TREES,
NO RESTORATION IN COUNTY RECORDS



Description of corner evidence found: SURVEYOR GENERAL RECORDS STATES:

SET 14" X 12" X 4" STONE FOR 1/4 SECTION CORNER BETWEEN SECTIONS 28 & 33.


Description of monument and accessories I established to perpetuate the

original location of this corner NO EVIDENCE WAS FOUND TO REESTABLISH THIS CORNER IN ITS ORIGINAL LOCATION.

AS NO EVIDENCE OF THE ORIGINAL CORNER WAS FOUND I SET A 2" & 36" GALVANIZED IRON PIPE 28" IN THE GROUND, WITH A ROCK MOUND AND 2 1/2" BRASS CAP MARKED:

NEW BEARING TREES:

A DOUGLAS FIR, 14" IN DIAMETER,
BEARS SOUTH 89° WEST, 72.4 FEET;
A PONDEROSA PINE, 12" IN DIAMETER,
BEARS SOUTH 21° EAST, 79.7 FEET;



REGISTERED
PROFESSIONAL
LAND SURVEYOR

George J. Cook

OREGON
JULY 14, 1961
GEORGE J. COOK
540

I HEREBY CERTIFY THE ABOVE CORNER MONUMENT WAS RE-ESTABLISHED AS HEREIN DESCRIBED ON SEPT. 8, 1973

WITNESSES:

S/ *John C. Blum*
S/ *Jack L. Smith*

Office of *County Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office for record on the *5th* day of *November*, 19*73*, at *11:00* o'clock *A.*m., (signed)
Robert W. Beyer by _____
(COUNTY OFFICIAL) (DEPUTY)