


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: NO HISTORY TO THE LOCATION OF THIS CORNER.




Description of corner evidence found: NONE

Description of monument and accessories I established to perpetuate the original location of this corner

SINCE THERE WAS NO EVIDENCE OF A CORNER SET I USED A SINGLE PROPORTION TO SET THIS CORNER MIDWAY BETWEEN THE CENTER WEST $\frac{1}{16}$ CORNER AND WEST $\frac{1}{16}$ CORNER. I SET A 2" X 36" GALVANIZED IRON PIPE 26" IN THE GROUND, WITH A ROCK MOUND AND A 2 $\frac{1}{2}$ " BRASS CAP MARKED:

NEW BEARING TREES:

A WHITE FIR, 12" IN DIAMETER, BEARS SOUTH 52° East, 32.5 FEET;
A DOUGLAS FIR, 12" IN DIAMETER, BEARS WEST, 36.0 FEET



REGISTERED
PROFESSIONAL
LAND SURVEYOR

George J. Cook

OREGON
JULY 4, 1961
GEORGE J. COOK
540

I HEREBY CERTIFY THE ABOVE CORNER MONUMENT WAS RE-ESTABLISHED AS HEREIN DESCRIBED ON SEPT. 8, 1973.

WITNESSES:

s/ *John E. Blunk*
s/ *Jack L. Smith*

Office of County Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 5th day of November, 1973, at 11:06 o'clock A.m., (signed)
Robert D. Dwyer by _____
(COUNTY OFFICIAL) (DEPUTY)