


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: CORNER WAS ESTABLISHED IN AUGUST 1874 BY ALONZO GESNER UNDER GENERAL LAND OFFICE CONTRACT NO. 206.

SURVEYOR GENERAL RECORDS STATES:

SET A STONE 16" X 12" X 4" FOR 1/4 CORNER BETWEEN SECTIONS 32 & 33.

NOTE: NO BEARING TREES
NO RESTORATION IN COUNTY RECORDS




Description of corner evidence found: I FOUND A MOUND OF ROCKS, BUT NONE MATCHING THE ROCK SET BY THE SURVEYOR GENERAL. ALSO FOUND WAS A 1/2" ROD WITH PLASTIC CAP OF UNKNOWN ORIGIN.

Description of monument and accessories I established to perpetuate the original location of this corner I SET A 2 1/2" X 36" GALVANIZED IRON PIPE 20" IN THE GROUND WITH A ROCK MOUND AND 2 1/2" BRASS CAP, MIDWAY BETWEEN THE SECTION CORNERS.

NEW BEARING TREES:

A PONDEROSA PINE, 7" IN DIAMETER, BEARS SOUTH 56° WEST, 134.0 FEET;
A PONDEROSA PINE, 16" IN DIAMETER, BEARS SOUTH 30° EAST, 76.0 FEET



I HEREBY CERTIFY THE ABOVE CORNER MONUMENT WAS RE-ESTABLISHED AS HEREIN DESCRIBED ON SEPT. 8, 1973.

WITNESSES:

s/ John C. Blunt
s/ Jack L. Smith



Office of County Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 5th day of November, 19 73, at 11:25 o'clock A.m., (signed)
Robert D. Beatty by _____
(COUNTY OFFICIAL) (DEPUTY)