

RECEIVED AND
FILE

JUL 28 1975
JOHN LIVEIRA, County Clerk

CORNER RESTORATION


By _____ Deputy

CORNER $E\frac{1}{4}$ Corner
Sec. 36 TWP 18 S., RANGE 26 E., W.M.

ORIGINAL SURVEY BY: George H. Thurston

CONTRACT NUMBER: 191

CONTRACT DATE: June 23, 1873



ORIGINAL DESCRIPTION:

40.00 Set stone 24x18x10 ins., 8 ins in grnd. Deposited marked stone for $\frac{1}{4}$ Sec. cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

June 17, 1975

Grant County Surveyor

EVIDENCE FOUND:

Found stone 18x15x6 marked $\frac{1}{4}$ loosely set in ground. Cor. is 10 ft. West of a North-South fence line. This corner is about 40 chains North of Twp. corner as I rough chained this distance to find the $\frac{1}{4}$ corner.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.


I set a $1\frac{1}{2}$ " x 30" iron pipe 22" in the ground with brass cap marked as shown from which NEW BEARING TREES:

An 18" Pine bears N. 68° E. 4.1 ft. marked $\frac{1}{4}$ S31 BT

A 6" Fir bears N. 43° W. 36.4 ft. marked $\frac{1}{4}$ S36 BT

I buried the original stone North and alongside pipe, and surrounded pipe with mound of stone to brass cap. Used compass with 20° E. Var. and steel tape, measuring to face of blaze on BT's.

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

X-25