

RECEIVED AND
FILE

JUL 28 1975
John Liveira
JOHN LIVEIRA, County Clerk

CORNER RESTORATION


By _____ Deputy

S $\frac{1}{4}$ Corner
CORNER Sec. 36 TWP 18 S., RANGE 26 E., W.M.

ORIGINAL SURVEY BY: Alonzo Gesner

CONTRACT NUMBER: 206

CONTRACT DATE: July 10, 1874



ORIGINAL DESCRIPTION:

Set stone 26x18x12 for $\frac{1}{4}$ Sec cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

June 17, 1975

Grant County Surveyor

EVIDENCE FOUND:

I found a stone 18x8x26 ins. loosely set in a mound of stone faintly marked $\frac{1}{4}$, 3'
South of an East-West fence.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

I set a 1 $\frac{1}{2}$ "x30" iron pipe 24" in the ground with brass cap marked as shown from which:

A 24" pine snag bears N. 63° E. 26.3 feet with old blaze
facing corner with no marks visible and Forest Service
location tag dated 1941 is on the tree.

A 26" pine bears S. 25° W. 29.5 feet with a Forest Service
location tag dated 1941 facing corner.

MONUMENT MARKED

NEW BEARING TREES:

An 8" pine bears N. 3° W. 19.1 feet marked $\frac{1}{4}$ S 36 BT

A 6" pine bears S. 44° W. 34.8 feet marked $\frac{1}{4}$ S 1 BT

I buried the original corner stone alongside and Southwest
of pipe and surrounded pipe with a mound of stone to brass
cap. Used compass and steel tape. 20° East variation,
Complete and File with Office of the Grant measured to face of
County Surveyor, Grant County, Oregon, blaze on BT's.

Courthouse, Canyon City, Oregon 97820

