


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



No record of subsequent monumentation found in Grant County survey records.

Description of corner evidence found:
Corner not previously established.
See map of survey 1149 dated June, 1990.

Description of monument and accessories I established to perpetuate the
original location of this corner: At position determined by survey, I cut a 5 inch cross in bed
rock, and painted the area red, from which:

New BTs, and, or BOs:
A 5/8" x 30" rebar with plastic cap marked "BGA SURVEY MARKER" bears N40°E, 8.25 feet.
A 5/8" x 30" rebar with plastic cap marked "BGA SURVEY MARKER" bears South, 6.00 feet.

Raised a mound of rock, 5' base around the cross.

Set a steel fencepost approximately 5 feet East with
land survey monument sign attached.

I hereby certify that the above corner point was
perpetuated as hereon described on June 14, 1990.

Witnesses:
Larry Pitcher
Curt Silva

Cut a 5" X
in bed rock



I used a steel tape and magnetic compass in the
establishment of new accessories. I used 18°
East magnetic declination and the distances are
to a 50d spike driven into the right side of the
root crown. I attached a brass washer marked
OPLS 644 to the BT blaze.

Office of... Surveyor ... County of... Grant ...
State of... Oregon ... I hereby certify that the within instrument was filed in this office
for record on the... 17 day of... July ... , 19... 90 ...
... Robert D. Bageot ... by ...
(COUNTY OFFICIAL) (DEPUTY)