

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original GLO survey by Alonzo Gesner under
Contract No. 206 dated July 10, 1874.

Field Notes State: N 89° 39' W, 39.95 CHS - Set
12" X 10" x 6" marked stone for 1/4 sec. cor.

DIAGRAM

T18S R27E
S 8
1/4 ——— S 17


Description of corner evidence found:

Not Found

Description of monument and accessories I established to
perpetuate the original location of this corner:

On May 9, 1994 at the location of the corner I set a 5/8" iron
pin with a 1 1/2" Alum. cap stamped "PLS 1288 1994 MAPS", with a
steel fence post next to the corner.

Bearing Tree reference points established as shown below. Each
B.T. reference point was blazed with a B.T. sign attached. B.T.
signs scribed with corner location and "C. T. Palmer, PLS 1288".



Witness: Toby Moss
Ref. Grant Co. Survey No. 1335

Office of County Surveyor, County of Grant, State of Oregon, I
hereby certify that the within instrument was filed in this
office for record on the 21 day of July, 1994.

Robert D. Beyer by _____
County Official Deputy