


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



No record of subsequent monumentation found in Grant County survey records.

Description of corner evidence found:
Corner not previously established.
See map of survey 1149 dated June, 1990.

Description of monument and accessories I established to perpetuate the
original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum
pipe with aluminum cap marked as shown, 20 inches in the ground, from which:



New BTs:
A 12 inch diameter Juniper bears N64°E, 78.96 feet marked N 1/16 S15 BT, in a single blaze.
A 17 inch diameter Juniper bears N79°W, 20.62 feet marked N 1/16 S 16 BT.

Set a steel fencepost approximately 5 feet East with
land survey monument sign attached.

Raised a mound of stone around monument, 4 ft. base to top of cap.

I hereby certify that the above corner point was
perpetuated as hereon described on May 30, 1990.

Witnesses:
Monty Gibson
Curt Silva



I used a steel tape and magnetic compass in the
establishment of new accessories. I used 18°
East magnetic declination and the distances are
to a 50d spike driven in the right side of the
root crown. I attached a brass washer marked
OPLS 644 to the BT blaze.

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of July, 1990
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)