

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original GLO survey by Alonzo Gesner under
Contract No. 206 dated July 10, 1874.

DIAGRAM

T18S R27E
SE 1/16
S 17



Description of corner evidence found:

Not Set During G.L.O. Survey.

Description of monument and accessories I established to
perpetuate the original location of this corner:

On May 10, 1994 at the location of the corner I set a 5/8" iron
pin with a 1 1/2" Alum. cap stamped "PLS 1288 1994 MAPS", with a
steel fence post next to the corner.

Bearing Tree reference points established as shown below. Each
B.T. reference point was blazed with a B.T. sign attached. B.T.
signs scribed with corner location and "C. T. Palmer, PLS 1288".



RENEWAL DATE
1-1-95

Witness: Toby Moss
Ref. Grant Co. Survey No. 1335

Office of County Surveyor, County of Grant, State of Oregon, I
hereby certify that the within instrument was filed in this
office for record on the 21 day of July, 1994.

Robert D. Boyer by _____
County Official Deputy

M-8