

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-23

History of original corner establishment:

Corner was originally established under G. L. O. contract No. 206, by Alonzo Gesner, on August 26, 1874. Surveyors General's notes state: "Set stone 12 X 10 X 8 for 1/4 Sec. cor."

DIAGRAM

T18S R27E
S24
1/4 
S25

Description of corner evidence found:

Found no trace of record stone or mound. Area has been logged and corner position is at edge of skid trail.

Description of monument and accessories | established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" aluminum pipe and cap
Marked:

Set pipe 24" in the ground and mound of stone around to cap.

From which by T-2 and EDM: A 9" Pine bears S63°E, 58.6 ft. scribed 1/4 S25 BT. A 16" Fir bears N18°W, 63.1 ft.

scribed 1/4 S24 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on the BTs. Placed 54-2 and 54-4 on a steel fence post 5' west and 54-2 on a steel fence post 5' east of the corner.

T18S R27E
S24
1/4 
S25
OR PLS 1051
1982

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel T. Rowland
Larry D. Shirley

August 5, 1982

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

**OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051**

Office of.....County Surveyor.....County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the.....28.....day of.....Oct....., 19..82
.....*Robert D. Dwyer*.....by.....
(COUNTY OFFICIAL) (DEPUTY)