


CERTIFIED RECORD OF LAND CORNER MONUMENTATION**History of original corner establishment:**

The original GLO survey was done by Henry W. Cooke under contract no. 494, dated January 16. 1884.

**Description of corner evidence found:**

This corner was not set under the original GLO contract. Nothing found.



Description of monument and accessories | established to perpetuate the original location of this corner:

On 11/14/86 at the proportioned location we set an all alum. monument, 2½" dia. x 30" long, with a 3" dia. cap stamped "W 1/16, C-C, S 1, T 18 S, R 28 E, WM, PLS 1288, 1986", buried 16", 14" above the ground in a mound of stone. Set steel fence posts 3' south and west with land survey and boundary signs attached.

A reference monument bears N 52°25'W, 17.7 feet.

A reference monument bears N 49°27'E, 17.8 feet.

Both reference monuments are 5/8" dia. steel pins with alum. caps stamped "RM, MAPS, PLS 1288, 1986".



GRANT COUNTY
SURVEY # 968

Office of SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 6 day of apr, 1987
Robert D. Dugan by _____
(COUNTY OFFICIAL) (DEPUTY)