


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original GLO survey was done by Bamford Robb under contract no. 366, dated August 18. 1880.



Description of corner evidence found:



This corner was not set under the original GLO survey. Nothing found.

Description of monument and accessories I established to perpetuate the original location of this corner:

On 11/13/86 at the proportioned location, we set an all alum. monument, 2½" dia. x 30" long, with a 3" dia. cap stamped "N 1/16, S 12, S 7, T 18 S, R 28 E, R 29 E, WM, PLSS1288, 1986", buried 20", 10" above the ground in a stone mound. Set steel fence posts 3' west and east with land survey and boundary signs attached.

A 6" w fir bears S 56°07'E, 18.0 feet scribed "N 1/16, S 7, BT"
A 6" w fir bears S 41°55'W, 27.8 feet scribed "N 1/16, S 12, BT"

Both BT's have a 6" band of red paint, BT and LS signs and a brass washer stamped "PLS 1288" set at the base.



GRANT COUNTY
SURVEY # 968

Office of SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 6 day of SEP, 1987
Robert D. Engle by _____
(COUNTY OFFICIAL) (DEPUTY)