

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-2

History of original corner establishment:

None.

DIAGRAM

T18S R28E
S19
W ~~1~~ 1/16
S30

Description of corner evidence found:

Not set.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" aluminum pipe and cap marked:
Set pipe 24" in the ground and mound of stone around to cap.
From which by magnetic declination of N20°E: A 9" Pine bears
N17°E, 19.4 ft. scribed W1/16 S19 BT. A 12" Fir bears S11°E,
17.8 ft. scribed W1/16 S30 BT. Painted blazes red and 6" red
band around. Placed 54-3s, 54-9s and brass washers stamped PLS
1051 on the BTs. Placed 54-2 and 54-9 on a steel fence post 5' north and 54-2
on a steel fence post 5' west of the corner.

T18S R28E
S19
W ~~1~~ 1/16
S30
OR PLS 1051
1982

I hereby certify that the above
corner monument was established
as herein described.

Witnesses: Daniel T. Rowland
Larry D. Shirley

August 4, 1982

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour
OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor.....County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...28...day of...Oct...1982
Robert D. Gay by
(COUNTY OFFICIAL) (DEPUTY)