

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-3

History of original corner establishment:

Corner was originally established under G. L. O. contract No. 494, by Henry W. Cooke, on March 28, 1884. Surveyor General's notes state: "Set a Basalt stone 16 X 14 X 10 ins. 11 ins. in ground for 1/4 sec. cor. marked 1/4 on N. face. From which, A pine 30 ins. dia. bears N78°W, 218 lks. dist. marked 1/4S BT. No other trees within limits and raised a mound of stone alongside."

DIAGRAM

T18S R28E
S19
1/4 —+—
S30

Description of corner evidence found:

Found no trace of record stone or mound of stone. Corner falls on steep rocky northeast slope. An east-west fence is 30' north of corner position and rocks may have been taken from the area for rock jacks. Found 36" Pine, scribed 1/4S BT. Measured S78°E, 143.9 ft.

Description of monument and accessories established to perpetuate the original location of this corner:

At measured point set 2 1/2" X 30" aluminum pipe and cap marked: Set pipe 22" in the ground and mound of stone around to cap. From which by magnetic declination of N20°E:
A 12" Pine bears S28°E, 22.0 ft. scribed 1/4 S30 BT. Painted blazes red and 6" red band around. Placed 54-3, 54-4 and brass washer stamped PLS 1051 on new BT. Place 54-3 and 54-4 on the old BT. Painted blazes red and 6" red band around. Placed 54-2 and 54-4 on a steel fence post 5' north and 54-2 on a steel fence post 5' east of the corner.

T18S R28E
S19
1/4 —+—
S30
OR PLS 1051
1982

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel T. Rowland
Larry D. Shirley

July 29, 1982

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor.....County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...28... day of...Oct... , 1982.
Robert D. Sigler by
(COUNTY OFFICIAL) (DEPUTY)