

CERTIFIED RECORD OF LAND CORNER MONUMENTATION**History of original corner establishment:**

The original GLO survey was done by Bamford Robb under contract no. 366, dated August 18, 1880.

DIAGRAM

T 18 S, R 29 E
W M
NE 1/16
S 7

Description of corner evidence found:

This corner was not set under the original GLO survey. Nothing found.



Description of monument and accessories | established to perpetuate the original location of this corner:

On 11/13/86 at the proportioned location, we set an all alum. monument, 2½" dia. x 30" long, with a 3" dia. cap stamped "NE 1/16, S 7, T 18 S, R 29 E, WM, PLS 1288, 1986", buried 24", 6" above the ground. Set steel fence posts 3' north and west with land survey and boundary signs attached.

A 8" p pine bears S 42°50'E, 42.3 feet, scribed "NE 1/16, S 7, BT"

A 6" mtn mahogany bears S 42°52'W, 40.3 feet, scribed "NE 1/16, S 7, BT"

Both BT's have a 6" band of red paint, BT and LS signs and a brass washer stamped "PLS 1288" set at the base.



Office of SURVEYOR County of CLATSOP
State of OREGON I hereby certify that the within instrument was filed in this office
for record on the 24 day of SEPTEMBER, 1980
Robert D. Sargent by _____
(COUNTY OFFICIAL) (DEPUTY)

CLATSOP COUNTY
SURVEY # 968