


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



P-3
F.B.4 Pg. 18

Description of corner evidence found:


None.

Description of monument and accessories established to perpetuate the original location of this corner:

At calculated position as determined by traverse swing tie, set a 2 1/2 inch O.D.X30 inch long aluminum pipe 24 inches in ground to bedrock with 3 1/4 inch aluminum cap marked as shown:

Marked new bearing trees:

a 9" Juniper bears South 44°15' East, 10.7 ft., scribed-C1/4S19BT;
an 18" Juniper bears South 51°15' West, 80.0 ft., scribed-C1/4S19BT.




M.V.18°30'E.

Raised a stone and earth mound 2 foot diameter to cap. Painted red band and faces red and nailed signs 54-9 and 54-3 on bearing trees. Set steel post 5 feet East with sign 54-9 facing corner. Nailed brass washer stamped "AS&E LS1026" to face of new bearing trees.

I hereby certify the above corner monument was established as herein described on May 24, 1985.

Witnesses: David B. Armstrong
Andy Dodson



Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*15*..... day of.....*July*....., 19.....*85*.....
.....*Robert D. Blythe*..... by.....
(COUNTY OFFICIAL) (DEPUTY)