

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Corner established by Bamford Robb under
General Land Office Contract No. 366 dated
August 18, 1880.

Surveyor General's records state:

North between Secs 19 and 20

Var 18°30'E

40.00 Set stone 16X12X12 in mound of stone
for 1/4 sec. cor.



P-5
F.B. 4 Pg.5 & 6

Description of corner evidence found:

No evidence found. Corner vicinity contains much surface stone.
No marked stones nor stone mounds considered original were found.
Corner determined lost and re-established by single proportion
between the section corners.

Description of monument and accessories | established to perpetuate the
original location of this corner:

At single proportionate position set by survey,
set 2 1/2 inch O.D. 30 inch long aluminum pipe
13 inches in ground to bedrock with 3 1/4 inch
aluminum cap marked as shown:

Marked new BT's:

a 12" Ponderosa Pine bears South 74°30' East,
44.4 ft., scribed-1/4S20BT;
a 10" Ponderosa Pine bears South 57°30' West,
30.2 ft., scribed-1/4S19BT.

Raised stone mound 4 foot diameter to cap. Painted
red band and faces red and nailed signs 54-3 and 54-4
on bearing trees. Set steel post 5 feet South with
sign 54-4 facing corner. Nailed brass washer stamped
"AS&E LS1026" to face of new bearing trees.

I hereby certify the above corner monument was re-established
as herein described on May 13, 1985.

Witnesses: David B. Armstrong
Daniel N. Patterson



M.V. 19° E.

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*15*..... day of.....*July*....., 1985
.....*Robert D. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)

