

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original Corner established in 1879 by McKinsie and Eckelson under GLO joint contract No. 328.

Survey General Records state:


A pine tree 12" in dia. for $\frac{1}{4}$ Sect. Cor. from which:

A 14" pine bears S 10° W, 20 lks dist.

A brass cap was set in 1978 by Sherman E. Anderson. Mr.

Anderson found and accepted a 14" stump as cor. tree, and

I agree. However, Mr. Anderson set his brass cap at recprd dist. from the bearing tree. I am using the center of the corner tree as the $\frac{1}{4}$ corner.




Description of corner evidence found:

Found 14" corner tree with the lower tip of a blaze from which a 16" pine stump scribed S BT bears S 60° W, 14.4 feet

Found 2" pipe with brass cap marked as shown N 83° W, 1.16 feet

Found new BTs by Anderson

See map of survey dated September, 1979



Description of monument and accessories I established to perpetuate the original location of this corner:

None



Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 24 day of Oct, 1979
Robert D. Bryant by _____
 (COUNTY OFFICIAL) (DEPUTY)