


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The SE 1/16 corner of Section 18 not previously established of record.

I established this 1/16 corner at intersection of lines from opposite corresponding 1/16 corners of the SE 1/4 of Section 18.



Description of corner evidence found:

None

(See map of Survey dated September, 1979)

Description of monument and accessories I established to perpetuate the original location of this corner:

At corner point I set 2 1/2"x30" iron pipe with brass cap marked as shown, 26" in ground, from which:

A 10" Juniper bears S 12 W, 22.1 ft., marked
SE1/16 S18 BT.

A 20" Ponderosa Pine bears N 89 W, 28.5 ft., marked
SE1/16 S18 BT.

Raised mound of stone.



Nailed brass washer to BT blazes,
used steel tape and magnetic compass
with 17° East declination measured
to center of BTs.



Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 24 day of Oct, 1979
Robert D. Sargent by _____
(COUNTY OFFICIAL) (DEPUTY)