


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

Nothing found.

Corner lies on fairly steep SW slope, 150 ft. north of draw running NW, and 30 ft. west of north/south fence.

Description of monument and accessories | established to perpetuate the original location of this corner:

On Aug. 18, 1983 at the calculated corner position I set a standard U.S. Forest Service all aluminum monument, 2 $\frac{1}{2}$ " dia. x 30" high, with a 3" cap stamped:

Monument buried 16", 14" above the ground, in a 12" high x 30" dia. stone mound.

Set stl. fence post with land survey corner alongside.



New BT's

A 12" p. pine bears S.10°W., 7.5 ft. scribed "C $\frac{1}{4}$ S22,BT"

A 10" p. pine bears N.25°W., 3.0 ft. scribed "C $\frac{1}{4}$,S22,BT"

BT's have a 6" band of red paint, BT & attention signs, and a brass washer with "PLS 1287" at the base.

Witnesses: P. Zabala, M. Walker .



Office of.....Surveyor.....County of.....Grant
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the...27... day of...Dec...19...83
Robert D. Bazar... by
(COUNTY OFFICIAL) (DEPUTY)