


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

Nothing found.

Corner lies on the south edge of rock slide with very large boulders, and 25 ft. west and 15 ft. north of where north/south fence line ends at rock slide.

Forest boundary posted north and south from corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

On Aug. 18, 1983 at the calculated corner position I marked a large boulder with "X, C $\frac{1}{4}$ ". Setting of a monument impracticable.



Set. stl. fence post with location tag and land survey corner sign 1.3 ft. NE of corner point.

New BT's

A 18" p. pine bears S.10°50'E., 43.0 ft. scribed "C $\frac{1}{4}$, S34, BT"

BT has a 6" band of red paint, BT & attention sign, and a brass washer with "PLS 1287" at the base.

Witnesses: M. Walker, P. Zabala



Office of..... Surveyor..... County of..... Grant
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the 27 day of Dec, 1983
Robert D. Bayless by.....
(COUNTY OFFICIAL) (DEPUTY)