

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAM

T18S R32E W.M.

S1/16 $\begin{matrix} C \\ | \\ C \end{matrix}$ S 34

Grant Co., Ore.

Description of corner evidence found:

Nothing found.

Corner lies approx. 100 ft. east of north/south fence. Forest boundary posted north from corner.

Description of monument and accessories established to perpetuate the original location of this corner:

On Aug. 18, 1983 at the calculated corner position I set a standard U.S. Forest Service all aluminum monument, 2 $\frac{1}{2}$ " dia. x 30" high, with a 3" cap stamped:

Monument buried 24", 6" above the ground, in a 4" high x 24" dia. stone mound.

Set stl. fence post with boundary and land survey corner sign north of corner.



New BT's

A 8" p.pine bears N.86°20'E., 37.6 ft. scribed
"N1/16, S34, BT"

A 8" p.pine bears N.33°W., 14.6 ft. scribed
"N1/16, S34, BT"

BT's have a 6" band of red paint, BT & attention signs, and a brass washer with "PLS 1287" at the base.

Witnesses: P. Zabala, M. Walker



Office of.....Surveyor.....County of.....Grant
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...27... day of...Dec...1983
Robert D. Boyer by.....
(COUNTY OFFICIAL) (DEPUTY)