


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Refer to: Plat of Wilson 1985 Cadastral Survey  
Section 29, T.7S., R.27E., W.M.

History of original corner establishment:

No record of previous monumentation.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner point I set a 2 1/2" X 30" alum. pipe with a 3" alum. cap containing a magnet and marked:

I built a stone mound around the monument.

S29  
C-W-W-NE  
1/256  
PLS 1832  
1986

From the corner:

A Ponderosa Pine, 10" dia., N57°E, 24.2 ft.

marked: C W W NE 1/256 S29 BT

A Ponderosa Pine, 10" dia., S15 1/2°E, 24.6 ft.

marked: X at breast height and BT at base.

A Ponderosa Pine, 13" dia., N76°E, 35.0 ft.

marked: C W W NE 1/256 S29 BT

BTs have blaze and a 6" stripe painted red, a BT tag, a "Land Survey Monument" sign and an alum. "PLS 1832" washer nailed to the bottom of the blaze. There is a 6' steel fence post with a "Land Survey Monument" sign within 5' of the corner.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at 20°E.

April 13, 1986 // July 1, 1986 add BT.

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 25 day of July, 1986  
Robert D. Taylor (COUNTY OFFICIAL) Fayette S. Munro (DEPUTY)

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 13, 1979  
FAYETTE S. MUNRO  
1832