


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1885 by Frank W. Campbell, under General Land Office, Contract no. 521.



Surveyor Generals Records State:

Set basalt stone 14x10x8 for 1/4 cor., marked 1/4 on W face, from which:

A 10" pine bears S68E, 159 lks.
Raised on mound of stone along side.

No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

Found stone, call size in a mound of stone marked 1/4, from which:

Original B. T.

A 22" Pine, in good condition, bears N 71° E, 110.5 ft. Scribes visable.

(Blaze faces corner--original bearing probably recorded in wrong quadrant)

Description of monument and accessories established to perpetuate the original location of this corner

At position of original stone, set 2 1/2" x 30" iron pipe, with brass cap marked as shown, 24" in ground. Raised mound of stone 5 ft. at base to top of cap, from which, new BTs:

A 10" Juniper bears S 31 W, 188.8 ft. marked 1/4 S 5. T 7 S. R 28 E. BT.


Nailed brass washer in BT blaze.

Set steel fence post 5 1/4 ft. south of corner.

Burried original stone north and alongside pipe, used steel tape and magnetic compass with 20° E declenation, measured to center of new BT and face of blaze on original BT.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1954
DUANE I. GRIFFITH
644



Office of County Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 8th day of August 1974.
Robert D. Barrett by _____
(COUNTY OFFICIAL) (DEPUTY)

Witnessed by
Betty Dowary

C-9