


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.



No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2 1/2" x 30" iron pipe 15" in ground with brass cap marked as shown from which I scribed bearing trees:


- A fir 11 in. diam. brs. N 32°40' E 31.30 ft. marked T6S R33E W 1/16 S31 BT
- A fir 13 in. diam. brs. S 39°20' W 25.00 ft. marked T7S R33E W 1/16 S6 BT

Nailed a brass washer marked PLS 933 to the BT blaze of all trees. Raised stone mound around pipe. Set steel post 3 ft. West of corner. Corner is West 150 ft. from a road which runs N-S. Used T-2 and steel tape, measuring a horizontal distance to the center of the bearing trees.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David H. Krumbain

OREGON
JULY 17, 1970
DAVID H. KRUMBEIN
933



Office of County Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 28 day of Sept 1978
Robert D. Bayart by _____
 (COUNTY OFFICIAL) (DEPUTY)