


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.



No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner

Set 2 1/2" x 30" iron pipe 6" in ground. Raised rock mound to brass cap. Brass cap marked as shown from which I scribed bearing trees:


- A pine 16 in. diam. brs. N 37° W 11.25 ft. marked N 1/16 S1 T7S R32E BT
- A pine 14 in. diam. brs. S 86° E 31.70 ft. marked N 1/16 S6 T7S R33E BT

Nailed a brass washer marked PLS 933 to the BT blaze of trees. Set a steel post 3 ft. South of corner. Used T-2 and steel tape measuring a horizontal distance to the center of the bearing trees.

REGISTERED PROFESSIONAL LAND SURVEYOR

David H. Klein

OREGON
JULY 17, 1970
DAVID H. KRUMBEIN
933



Office of _____ County Surveyor _____ County of _____ Grant _____
 State of Oregon _____, I hereby certify that the within instrument was filed in this office
 for record on the 22 day of Sept 1978
Robert D. Begett by _____
 (COUNTY OFFICIAL) (DEPUTY)

*SEE WELLS 12/89