

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed- Subdivided section.

DIAGRAM  
T. 7S., R. 33E  
W 1/16 C-C

No record of subsequent remonumentation found in County Record.

Description of corner evidence found:

NONE.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2½" x 30" iron pipe 25" in ground with brass cap marked as shown: from which I scribed bearing trees:

AAfir 16in. diam. brs. N 39°57' W 68.47ft. marked CW 1/16 S6 BT  
A fir 15in. diam. brs. S 16°10' E 23.15ft. marked CW 1/16 S6 BT

Nailed a brass washer marked PLS 933 to the BT blaze of trees. Set a steel post 4ft. North of corner. The corner is North 838ft. from road. Used T-2 and steel tape, measuring a horizontal distance to the center of the bearing trees

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*David H. Krumbein*  
OREGON  
JULY 17, 1970  
DAVID H. KRUMBEIN  
933

T 7S R 33E  
W 1/16  
C — C  
Sec. 6  
1978  
PLS 933

Office of.....County Surveyor..... County of Grant  
State of Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the 20 day of Sept. 1978  
*Robert D. Baggett* by.....  
(COUNTY OFFICIAL) (DEPUTY)